

From: Terry Seymour
Sent: 17 September 2023 12:59
To: Assistant Clerk | Arlesey Town Council
Subject: Faulty Column A4 Primrose Lane

EXTERNAL SENDER WARNING. This message was sent from outside your organisation. Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

EST TCS/JS 841
17/9/23

Hi Christine,

We have recently been out to look at faulty column A4 in Primrose Lane and found that the old 35 Watt SOX lantern to this column has burnt out and requires replacing. Coupled with this, the existing old cast iron column is in poor condition with the Electrical Supply intake position situated half way up the column in an even worse state, with corrosion and no effective seal against the weather. This old column requires replacing completely.

So to excavate a hole and disconnect and remove the existing old column completely and supply and fit 1 x new 5 MTR tubular galvanised steel column complete with a new Phosco 11 Watt LED lantern coupled with the necessary internal column fusing/isolation equipment as required and pay UKPN,s column transfer charges, the total cost of install with all the reinstatement works will be £ 1750.00 +vat, leaving the new column in full working order.

Regards Terry